

No. 10

Dated 07/02/2024

OFFICE NOTE

Subject: Estimated Proposal For Repair of Cardiac Ward Beds

**MAINTENANCE & ENGINEERING
DEPARTMENT ATM ATD**

DIARY NO. 158

DATED 8/2/24

Reference to subject above, feasibility report of cardiac beds is as follow,

Sr. No	Description	Cost per unit	Total No
OPTION A	01 Diamond Foam 4" height, length=78",width=36"		24
	02 Leatherette, LXW =(84x42)"		24
	03 Doori		24
	04 China Wheel 5" locable		96
	05 China Bed side table 2"		96
	06 China Bed over head table 2"		96
	07 Bed side IV stand		24
	08 Bed Strip 4", 3ftxlength,4x2 width with bending		96
	09 Bed side grill 4 feet,width=12",3/4 pipe with clips and spring		48
	10 Jack support 1.5x1.5, 200 foot		72
	11 Nuts & bolts		72
	12 Bed Jack brass china, rod 2 feet, jack got=3",single		24

Copy

sendi
with p

	nearing, 1.5 inch pipe=4feet	
13	Red oxide	4 gallon for 24 beds
14	Paint white or smoke grey	7 gallon for 24 beds
15	Petrol	34 liter for 24 beds
Total Expense on beds repairing with IV stands and patient side table including foam and leatherette installation		
New Beds with foam and leatherette		

Beds in Cardiology is 24 which will cost against option A i.e. repairing, F
ce and taxes while if we precede for option B i.e. new purchase, it will co

onstrain Rs. 1,394,040 feels to be very affordable in spite of buying new
case is forwarded to competent authority for approval please.

