

Dental Air Compressor Total = 15 NO

SR. NO	NAME OF EQUIPMENT	FAULT DIAGNOSED	REMARKS
1	Dental Air Compressor (Total = 15)	low pressure or perceived low pressure	Needs Complete overhauling and replacement of parts to maintain required pressure